

One-Way

Face Velocity		500	600	700	800	900	1000	1200	1400	1600	1800	2000
Pressure Loss		.020	.020	.030	.040	.050	.060	.090	.120	.160	.200	.250
22 x 22 Ak 1.330	CFM	665	800	930	1065	1195	1330	1595	1860	2130	2395	2660
	Throw	10-22	12-26	16-30	18-34	20-36	22-40	26-46	30-50	36-54	38-58	44-60
	NC	<20	<20	<20	20	23	26	30	34	38	41	44

Two Way

Face Velocity		500	600	700	800	900	1000	1200	1400	1600	1800	2000
Pressure Loss		.020	.020	.030	.040	.050	.060	.090	.120	.160	.200	.250
22 x 22 Ak 1.330	CFM	665	800	930	1065	1195	1330	1595	1860	2130	2395	2660
	Throw X/Y	8-17/8-17	9-20/9-20	2-23/12-23	4-26/14-26	5-27/15-27	7-30/17-30	0-35/20-35	3-38/23-38	7-41/27-41	9-44/29-44	3-45/33-45
	NC	<20	<20	<20	22	25	28	32	36	40	43	46

Four-Way

Face Velocity		500	600	700	800	900	1000	1200	1400	1600	1800	2000
Pressure Loss		.020	.020	.030	.040	.050	.060	.090	.120	.160	.200	.250
22 x 22 Ak 1.330	CFM	665	800	930	1065	1195	1330	1595	1860	2130	2395	2660
	Throw X/Y	5-11/5-11	6-13/6-13	8-15/8-15	9-17/9-17	0-18/10-18	1-20/11-20	3-23/13-23	5-25/15-25	8-27/18-27	9-29/19-29	2-30/22-30
	NC	<20	<20	<20	20	23	26	30	34	38	41	44

Three-Way

Face Velocity		500	600	700	800	900	1000	1200	1400	1600	1800	2000
Pressure Loss		.020	.020	.030	.040	.050	.060	.090	.120	.160	.200	.250
22 x 22 Ak 1.330	CFM	665	800	930	1065	1195	1330	1595	1860	2130	2395	2660
	Throw	5-11/8-17	6-11/9-20	8-15/12-23	9-17/14-26	0-18/15-27	1-20/17-30	3-23/20-35	5-25/23-38	8-27/27-41	9-29/29-44	2-30/33-45
	NC	<20	<20	<20	20	23	26	30	34	38	41	44